Manhole Inspection Summary M			Ma	anhole # S53	K044N	ЛΗ	
Printed On: 4/3/	2009				Page 1	of 3	
Inspection	☐ Is Incomplete	Rating: 3) Fair					
Record Plat: 53	BK Node: 044	Status: Found		Insp Date:	4/9/08 2:19	PM	
Incomplete Comments				Crew: mike			
				Inspector: jjoine	r		
				Firm: ATS			
Location	Address: 700 s ellwood			Cross Street: foster			
Manhole	Type: Terminal	_ocation: Alley	(Ground Conditions:	Dry		
	☐ Prev. Rehab	Weather: Dry	S	ubject To Ponding:	None		
Comments							
Cover	Shape: Circular	Diameter: 24	` ,	` ,		(in.)	
	Type: Sanitary	Condition: Sou		Cover Material: C	ast Iron		
Properties: Bolted Vented Water Tight Water Tight Insert							
Frame Offset: 0 (in.) Condition: ✓ Sound ☐ Cracked ☐ Leaks							
Chimney / Frame Adjustment							
Condition: Sound Cracked Root Intrusion Loose Brick Deteriorated							
Infiltration: ☐ None ☐ Joint ☐ Cracks ☐ Mortar ☐ Roots ☐ Wall							
Corbel	Material: Brick	☐ Parg	ed Type:	Concentric/Eccen	tric		
Condition:	✓ Sound ☐ Cracked ☐ Root Intrusion ☐ Loose Brick ☐ Deteriorated						
Infiltration:	Infiltration: ☑ None ☐ Joint ☐ Cracks ☐ Mortar ☐ Roots ☐ Wall						
Barrel	Material: Brick	☐ Parg	ed				
Shape:	Circular Dia	ımeter: 48 (in.) Len	gth: 0 (in.)				
Condition:	✓ Sound ☐ Cracke	ed Root Intrusion	Loose	Brick Deteriora	ated		
Infiltration:	✓ None ☐ Joint	☐ Cracks ☐ Mor	tar 🗌 Roo	ots 🗌 Wall			
Bench	Exists Material:		☐ Parged	t			
Condition:	☐ Sound ☐ Cracke	ed Root Intrusion	□ Deterior	orated Leaks	Debris		
Channel	Material: Brick	☐ Parg	ed				
Channel Exposure: Fully Open Junc Dist: 0 nearest .5 ft. Azimuth: 0							
Condition:	☐ Sound ☐ Cracke	ed Root Intrusion	□ Deterior	orated Leaks	✓ Debris		
Steps Count: 4 Missing: 2 Corroded							
Surcharge	Evidence Of Surc	harge Depth: 0	(ft.)	e Surcharge Prese	nt		

Manhole Inspection Summary

Manhole # S53K__044MH

Printed On: 4/3/2009 Page 2 of 3

Location View



Defect 1



channel debris

Top View



Manhole Inspection Summary

Manhole # S53K__044MH

Printed On: 4/3/2009 Page 3 of 3

8 in. Circular Gravity Sewer Pipe Out @ 12 OClock





Pipe Height: 0 (in.) Direct

Pipe Material: Clay

Invert Depth: 7.50 (ft.) Flow Characteristics: None

Deposits: ☐ None ☐ Mud ☐ Sludge ✓ Debris ☐ Grease

Silt Depth: **5** (in.) Deposits Extent: **Heavy**Infiltration: **None** Pipe Seal Cond: **Unknown**

Drop: **None**

Connects To: **Manhole**Possible Illicit Connection